

Name of Project:	UPGRADING OF RMSC TRACK OVAL	
Location:	RMSC, P. Ocampo Sr. St., Malate, Manila	
Date Prepared:	February 13, 2019	
Subject:	PROJECT SCOPE OF WORK	

This Scope of work is supplemental to the drawings but not limited to the following:

- 1. Mobilization of manpower and equipment.
- 2. Removal and replacement all of existing rubber at track, D-Sections.
- 3. Removal of damaged asphalt pavement at the track and D-Sections.
- 4. Base/Surface Preparations.
- 5. Supply and installation of Rubber Sandwich System.
- 6. Application of bituminous primer/tact coat.
- 7. Removal of existing embedded pole vault box discuss and hammer throw rings at D Section.
- 8. Cover all cylinders of throwing cage at D Section with concrete.
- 9. Repair concrete covers along the runway of steeple chase and insert pipes as water passages into the drainage.
- 10. Declogging and cleaning of internal and drainage of track oval.
- 11. Declogging and cleaning external drainage between track oval and bleachers.
- 12. Cleaning of Track and D-Sections areas prior to the spraying of bitumol.
- 13. Application of asphalt on Track and D-Sections.
- Repair all damaged concrete retainer on sides of the track and in between D-Sections and Football Field.

SPORTS COMMISSION A T990	PHILIPPINE SPORTS COMMISSION	Page No.:	Page 2 of 2
	SCOPE OF WORK	Revision No.:	0
	PSC-SOP-VFMS-02 F05	Effectivity:	3-01-19

Prepared by:

OSCAR A. PAPELERA JR.

Engineer II Date: _____

Checked/Reviewed by:

ENGR. PEDRO I. PINEDA, JR.

Head, Engineering & Maint. Section Date: _____

Noted By:

MR. MANUEL G. BITOG

Acting Chief, Sports Facilities Division

Recommending Approval:

DIR. MERLITA R. IBAY

OIC, Office of the Executive Director Date: _____

Approved by:

HON. WILLIAM I. RAMIREZ Chairman Date: _____